



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://nemnr.d.state.nm.us/ocd/District III/district](http://nemnr.d.state.nm.us/ocd/District%20III/district)

BRADENHEAD TEST REPORT
(Submit 2 copies to above address)

Date of Test 6-25-04 Operator Koch Exploration Co API #30-0 45-31824
Property Name Heard Com 20 Well No 20-1A Location: Unit P Section 20 Township 28N Range 10W
Pressure (Shut-In or Producing) Tubing Intermediate Casing Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes			Steady Flow	
10 minutes			Surges	
15 minutes			Down to Nothing <u>X</u>	
20 minutes			Nothing	
25 minutes			Gas	
30 minutes			Gas & Water	
			Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

REMARKS:

Bradenhead died in 2 or 3 seconds.
Baseline Test after drilling. Cement had come to
surface on longstring cement job.

By John Clark Witness
Prod Supt
(Position)