

NEW MEXICO ENERGY, MINIERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

	- 1		Black mus		
Date of Test_	9-21-04	Operator	Marcon Och	API #30-0 39 -	24309
Property Nam	ieJearella 464	Well No. <u>5</u>	Location: Unit B	Section 3 Townsl	nip 30 N Range 03W
Well Status(S	hut-In or Producing	Tubing 79	Intermediate 4/4 Ca	sing 106 Bradenho	ead_ Ø _
OPEN BRA	DENHEAD AND IN	TERMEDIATE '	TO ATMOSPHERE IND	DIVIDUALLY FOR 15	MINUTES EACH
TIME	PRESSURES: INTERMEDIATE	CASING		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes			Steady Flow_		
10 minutes			Surges_		
15 minutes			Down to Noth	ning	<u> </u>
20 minutes			Nothing		
25 minutes		·	Gas		
30 minutes			Gas & Water		
			Water		
If bradenhead	flowed water, check a	l of the descriptio	ns that apply below:		07.000
CLEA	R FRESH	SALTY	SULFUR BL	ACK	On the second
5 MINUTE SH	UT-IN BRADENH	EAD	INTERMEDIATE		3000
REMARKS:				<u> </u>	
	<u> </u>				
					
					·
By	DV SA	Wit	ness	<u> </u>	
(Positi	e Operato				