(Position)

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District/III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test	8-19-04	Operator ROB	ERT L. BAYLESS, PRODUCER LLC	API #30-0 <u>39-24642</u>	
Property Name	*		6 Location: Unit		30N Range 4W
Well Status (Shut-In or Producing) Tubing 57 Intermediate Casing 80 Brandenhead					
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH					
TIME	PRESSURES: INTERMEDIATE	CASING		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes	_6	95	Steady Flow	oq	
10 minutes	6	97	Surges	ه لم	
15 minutes	_	97	Down to Nothing		
20 minutes	<i>_</i>	97	Nothing	X	
25 minutes	\$	98	Gas		
30 minutes	6	98	Gas & Water	56789	777
			Water	SEP	
If bradenhead flowed water, check all of the descriptions that apply below: CLEAR FRESH SALTY SULFUR BLACK 5 MINUTE SHUT-IN BRADENDHEAD INTERMEDIATE A					
5 MINUTE SHUT-IN BRADENDHEAD INTERMEDIATE NA					
EVERYTHUNG LOOKED GOOD					
By Witness					