

NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIGHZZOS ROAD AZTEC NM 87410 (505) 334-6178 FAX: (505) 334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test_	4-2-09	Operator	Richardson	_API #30-0_ <i>+5</i>	-30031
			<u>y</u> Location: Unit M		
Well Status(S	hut-In or Producing	Tubing O	Intermediate Cas	ing /O Brandenh	nead O
OPEN BRA	DENHEAD AND IN	TERMEDIATE '	TO ATMOSPHERE INDI	VIDUALLY FOR 15	MINUTES EACH
TIME	PRESSURES: INTERMEDIATE	CASING		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes			Steady Flow		
10 minutes			Surges		
15 minutes		Down to Nothing			
20 minutes			Nothing		
25 minutes			Gas		
30 minutes	-		Gas & Water	•	
			Water		
If bradenhead flowed water, check all of the descriptions that apply below:					
CLEAR FRESH SALTY SULFUR BLACK					
5 MINUTE SH	UT-IN BRADENHI	EAD	INTERMEDIATE		
REMARKS:			-		
		· *** *** *** ***			
	A1-16-1				
Ву		Wit	ness		
Positi	Mgr jon)				