



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

RCVD JUL 20 '12

OIL CONS. DIV.

DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-20-12 Operator Burlington Res API #30-0 45 11 777

Property Name Thodes TLB Well No. 1 Location: Unit 20 Section 20 Township 28 Range 11

Well Status (Shut-In or Producing) Initial PSI: Tubing 31.9 Intermediate 21.1 Casing 31.3 Bradenhead 31.3

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead Int	Csg	INTERM Int	Csg
TIME					
5 min	0		31.6		
10 min	0		31		
15 min	0		32		
20 min	0		32		
25 min	0		33		
30 min	0		33		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow <u>/</u>	
Surges	
Down to Nothing	
Nothing	
Gas <u>/</u>	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 3.5 INTERMEDIATE

REMARKS:

Had blow first 16 seconds - to medium blow
at 32 seconds. really light blow at 5 minutes
to vapors at 10 minutes run off from Navajo irrigation 15 vapors

By Steve D. Lutz

Witness Nancy Cushing

(Position)

Schematic
gas analysis

20 "
25 "
30 "

E-mail address

Jet pump - Cleans out water
Actually set nozzle at end of tubing