



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

RCVD JUL 23 '12

OIL CONS. DIV.
DIST. 3

Date of Test 7-23-12 Operator COPC API #30-0 45-09025

Property Name Sammons Well No. 2 Location: Unit 6 Section 32 Township 30 Range 12

Well Status (~~Shut-In~~ or Producing) Initial PSI: Tubing 332 Intermediate — Casing 332 Bradenhead 40

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>—</u>	<u>332</u>		
10 min	<u>0</u>	<u>—</u>	<u>332</u>		
15 min	<u>0</u>	<u>—</u>	<u>332</u>		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	<u>/</u>	
Nothing		
Gas	<u>/</u>	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR — FRESH — SALTY — SULFUR — BLACK —

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 3 INTERMEDIATE —

REMARKS:

Bradenhead blew down in 20 sec.

By Garrett Gonzales
M50 Conoco Phillips
(Position)

Witness Paul Wade

E-mail address —