



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

RCVD JUL 23 '12

OIL CONS. DIV.

DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-23-12 Operator Burlington Co. API #30-0 45-09060

Property Name Murphy E Well No. 2 Location: Unit 34 Township 30 Range 11

Well Status (Shut-In or Producing) Producing Initial PSI: Tubing 102 Intermediate 0 Casing 102 Bradenhead 2.9

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead				
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	102	0	102
10 min	0	0	102	0	102
15 min	0	0	102	0	102
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow <u>to vapors</u>	
Surges	
Down to Nothing	
Nothing	<u>/</u>
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 4.6

INTERMEDIATE _____

REMARKS:

Gas Sample took - 30 on diaphragm tube
BH had blow to vapors i.e. 14 seconds. 5 min vapors -
10-15. Int. nothing when opened.

By JM
(Position)

Witness Mona Cochling
Request for schematic

E-mail address _____