



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

RCVD JUL 24 '12

OIL CONS. DIV.
DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-24-12 Operator COPC ~~Josh Proctor~~ API #30-0 45-26493

Property Name Morris Well No. 6 Location: Unit B Section 28 Township 30 Range 11

Well Status (~~Shut-In~~ or Producing) Initial PSI: Tubing — Intermediate — Casing 96 Bradenhead 6

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>—</u>	<u>99</u>		
10 min	<u>0</u>	<u>—</u>	<u>99</u>		
15 min	<u>0</u>	<u>—</u>	<u>99</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	☒
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR — FRESH — SALTY — SULFUR — BLACK —

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE —

REMARKS:

Blew down in 40 sec. Bradenhead

0 H₂S on Bradenhead

By g. albrite

Witness Paul Wike

(Position)

E-mail address —