



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

RCVD JUL 24 '12
OIL CONS. DIV.
DIST. 3

Date of Test 7-24-12 Operator COPC Josh Proctor API #30-0 45-32834

Property Name Morris Well No. 103 Location: Unit 4 Section 28 Township 30 Range 11

Well Status (Shut-In or Producing) Initial PSI: Tubing 27 Intermediate — Casing 47 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	—	47		
10 min	0	—	47		
15 min	0	—	47		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	✓
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR — FRESH — SALTY — SULFUR — BLACK —

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE —

REMARKS:

Nothing on the Bradenhead.

0 H₂S on Bradenhead 0 H₂S on cathodic well

By J. Proctor

Witness Paul W. W. W.

(Position)

E-mail address —