



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3ddistrict.htm](http://emnr.state.nm.us/ocd/District%20III/3ddistrict.htm)

RCVD JUL 24 '12

OIL CONS. DIV.
DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-24-12 Operator COPC Josh Proctor API #30-0 45-33579

Property Name Morris Com Well No. 1045 Location: Unit E Section 28 Township 30 Range 11

Well Status (Shut-In or Producing) Initial PSI: Tubing 18 Intermediate — Casing 32 Bradenhead 02

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0	—	33		
10 min	0	—	33		
15 min	0	—	33		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	✓
Nothing	
Gas	✓
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE —

REMARKS:

Braden head blew down in 6 seconds.

0 H2S on Braden head. 0 H2S on cathodic well.

By [Signature]

Witness Paul Weber

(Position)

E-mail address _____