



AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7-1-04 Operator C.D.X Rio, LLC API # 3003906402

Property Name Jicarilla B #1 Location: Unit G Section 22 Township 26 Range 5
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 210^{FF} Intermediate _____ Casing _____ Bradenhead 2[#]

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Intermediate	
	BH- Blowdown	Casing- Monitor	Intermediate- Monitor	Intermediate- Blowdown	Casing- Monitor	Flowed	Flowed
5 minutes						Steady Flow	
10 minutes						Surges	
15 minutes						Down to Nothing	<u>X 25 sec</u>
20 minutes						No Flow	
25 minutes						Gas	<u>X</u>
30 minutes						Gas and Water	
5 minute SI						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 0[#] Intermediate _____


REMARKS:

No place too take Casing Pressure

y Harry Whitson
Tech T.P.S
(Position)

Witness

David Spar



NMOCD Test Area: