



NEW MEXICO DEPARTMENT OF CONSERVATION AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7-1-04 Operator C.D.X Rio, LLC API # 300390812

Property Name Jicarilla B #6 Location: Unit K Section 22 Township 26 Range 5
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 60[#] Intermediate Casing 80[#] Bradenhead 70[#]

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>1</u> [#]	<u>80</u> [#]				Steady Flow	
10 minutes	<u>0</u> [#]	<u>80</u> [#]				Surges	
15 minutes	<u>0</u> [#]	<u>80</u> [#]				Down to Nothing <u>X 20 Sec.</u>	
20 minutes	<u>0</u> [#]	<u>80</u> [#]				No Flow	
25 minutes	<u>0</u> [#]	<u>80</u> [#]				Gas <u>X</u>	
30 minutes	<u>0</u> [#]	<u>80</u> [#]				Gas and Water	
5 minute St	<u>0</u> [#]	<u>80</u> [#]				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-In Bradenhead Intermediate

REMARKS: Bradenhead is too low too gauge

y Harry White
Tech T.P.S.
(Position)

Witness David Sp... T.P.S.

NMOCD Test Area: