



NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 10/14/04 Operator CDX GAS API # 3003920570

Property Name Jicavilla Contract #15524 ^{SW/SW} Location: Unit M Section 31 Township 26N Range 5W
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 45 Intermediate N/A Casing 145 Bradenhead 60

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>30</u>	<u>145</u>				Steady Flow	
10 minutes	<u>10</u>	<u>145</u>				Surges	
15 minutes	<u>0</u>	<u>145</u>				Down to Nothing	
20 minutes	<u>0</u>	<u>145</u>				No Flow	
25 minutes	<u>0</u>	<u>145</u>				Gas <u>Blew dv. to vapor</u>	
30 minutes	<u>0</u>	<u>145</u>				Gas and Water	
5 minute SI	<u>60</u>	<u>145</u>				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

REMARKS:

Blew dv. to vapor in 15 min. TSTM. No water. BU to 60psi in 5 min.

By Therover Vigil
Lease Operator
(Position)

Witness _____