



NEW MEXICO DEPARTMENT OF CONSERVATION, MINERALS AND NATURAL RESOURCES DEPARTMENT

Off. CONSERVATION DIVISION
AZTEC-DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7-23-04 Operator CDX Rio LLC API # 3003922088

Property Name Ticarilla Cont 155-22E Location: Unit K Section 31 Township 26 Range 5
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 52 Intermediate Casing 135 Bradenhead 10

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>0</u>					Steady Flow	
10 minutes						Surges	
15 minutes						Down to Nothing <u>30 Sec.</u>	
20 minutes						No Flow	
25 minutes						Gas <u>X</u>	
30 minutes						Gas and Water	
5 minute St						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black


5 Minute Shut-in Bradenhead 0 Intermediate

REMARKS:

John Lopez
T.P.S. Tech

(Position)

Witness _____



NMOCD Test Area: