



AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
 AZTEC-DISTRICT OFFICE
 1000 RIO BRAZOS ROAD
 AZTEC, NM- 87410
 (505) 334-6178 FAX: (505) 334-6170
 http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7-27-04 Operator CDX Rio, LLC API # 3003922564

Property Name Jicarilla CONT/55#031 Location: Unit H Section 29 Township 26 Range 5
 (Well Name and Number)

Pressure (Shut-in or Producing) Tubing 65" Intermediate _____ Casing 65" Bradenhead

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH.


Time	Bradenhead			Intermediate		Flow Description	Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor			
5 minutes	<u>0#</u>					Steady Flow		
10 minutes						Surges		
15 minutes						Down to Nothing		
20 minutes						No Flow <input checked="" type="checkbox"/>		
25 minutes						Gas		
30 minutes						Gas and Water		
5 minute SI						Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead Intermediate _____

REMARKS:



Darnell Green
TECH
 (Position)

Witness _____

NMOCD Test Area: