



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

Oil CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7-26-04 Operator CDX RIO LLC API # 3003922570

Property Name Sicarilla cont 155 #030 Location: Unit D Section 30 Township 26 Range 5
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 60" Intermediate _____ Casing 60" Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Flow Description
	BH- Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor	
5 minutes	<u>0</u>					Steady Flow
10 minutes						Surges
15 minutes						Down to Nothing
20 minutes						No Flow <u>0</u>
25 minutes						Gas
30 minutes						Gas and Water
5 minute St						Water

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____


5 Minute Shut-in Bradenhead 0 Intermediate _____

REMARKS:

Daniel G. ...
Tech

(Position)

Witness _____



NMOCD Test Area: