



NEW MEXICO DEPARTMENT OF ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

Oil CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7-27-04 Operator CDX Rio, LLC API # 3003922898

Property Name Jicarilla A #006E Location: Unit E Section 20 Township 26 Range 5
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 220" Intermediate Casing 225" Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead	Intermediate
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	<u>0#</u>						Steady Flow	
10 minutes							Surges	
15 minutes							Down to Nothing	
20 minutes							No Flow <u>X</u>	
25 minutes							Gas	
30 minutes							Gas and Water	
5 minute St							Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead 0 Intermediate

REMARKS:

Danell Speer
Tech

(Position)

Witness _____

NMOCD Test Area:

