



NEW MEXICO DEPARTMENT OF ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7-27-04 Operator CDX Rio, LLC API # 3003923808

Property Name Jicarilla Cont 155 #033A Location: Unit C Section 29 Township 26 Range 5
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 65" Intermediate Casing 75" Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Flow Description	Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor			
5 minutes	<u>0#</u>					Steady Flow		
10 minutes						Surges		
15 minutes						Down to Nothing		
20 minutes						No Flow <u>X</u>		
25 minutes						Gas		
30 minutes						Gas and Water		
5 minute St						Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead 0 Intermediate

REMARKS:

Darrell Green
Tech

(Position)

Witness _____

NMOCD Test Area:

