

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
Aztec District Office
1000 Rio Brazos Road
Aztec NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://nemnr.state.nm.us/ocd/District III/3district.htm](http://nemnr.state.nm.us/ocd/District%20III/3district.htm)


BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6-8-04 Operat PATINA SAN JUAN, INC. API# 30-039-06811
Property Name CHAMPLIN Well No. 2 Location: Unit J Section 35 Twp 27N Range 04W
Pressure (Shut-in or Producing) Producing Tubing 30 Intermediate Ø Casing 40 Bradenhead Ø

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes	<u>40</u>		Steady Flow	
10 minutes	<u>40</u>		Surges	
15 minutes	<u>40</u>		Down to Nothing	
20 minutes			Nothing	<u>N/A</u>
25 minutes			Gas	
30 minutes			Gas & Water	
			Water	



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD Ø INTERMEDIATE _____

REMARKS:

By Larry Bingham Witness _____
Pumper
(Position)