NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION

Aztec District Office

1000 Rio Brazos Road

Aztec NM 87410

(505) 334-6178 FAX: (505) 334-6170

http:\lemnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6-10-04 Operato PATINA SAN	JUAN, INC.	_API#	30-039-06896
Property Name CHAMPLIN Well No. 5	Location:Unit	K Section	25 Twp 27N Range 04W
Pressure (Shut-in or Producing) Tubing	Intermediate	<u>O</u> Casing	<i>4</i> ∂ Bradenhead ○
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH			
PRESSURES: TIME INTERMEDIATE CASING		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes 42	Steady Flow	<u></u>	
10 minutes 4 P	Surges	6/\	
15 minutes 4D	Down to Nothin	g <u>N/4</u>	
20 minutes	Nothing	yes	
25 minutes	Gas	'NO	
30 minutes	Gas & Water		
	Water	NO	
If bradenhead flowed water, check all of the descriptions that apply below:			
CLEARFRESH	SALTY	SULFUR	BLACK
5 MINUTE SHUT-IN BRADENHEAD OF SI	_ INTERMEDIAT	E	89101112137
			10 JUL 200
			W 000000 B
By Sinc Brss Witness			Co. 3 IV.
(Position)			CC 1202 97 12 18