

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
Aztec District Office  
1000 Rio Brazos Road  
Aztec NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
[http://nemnr.state.nm.us/ocd/District III/3district.htm](http://nemnr.state.nm.us/ocd/District%20III/3district.htm)

**BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test 6-9-04 Operat PATINA SAN JUAN, INC. API# 30-039-21485

Property Name CHAMPLIN Well No. 5A Location: Unit F Section 25 Twp 27N Range 04W

Pressure (Shut-in or Producing) Tubing X Intermediate 0 Casing 50 Bradenhead 0  
40

**OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH**

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes		<u>50</u>	Steady Flow <u>NO</u>	
10 minutes		<u>50</u>	Surges <u>NO</u>	
15 minutes		<u>50</u>	Down to Nothing <u>NO</u>	
20 minutes			Nothing <u>yes</u>	
25 minutes			Gas <u>NO</u>	
30 minutes			Gas & Water <u>NO</u>	
			Water <u>NO</u>	

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN BRADENHEAD 0.78 INTERMEDIATE \_\_\_\_\_

REMARKS:

By Isaac Bass Witness \_\_\_\_\_

(Position)

