

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
Aztec District Office
1000 Rio Brazos Road
Aztec NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emmr.state.nm.us/ocd/District/III/3district.htm>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)


Date of Test 6-9-04 Operat PATINA SAN JUAN, INC. API# 30-039-21521

Property Name CHAMPLIN Well No. 3A Location: Unit F Section 35 Twp 27N Range 04W

Pressure (Shut-in or Producing) Tubing 20 Intermediate 0 Casing X Bradenhead 0
30

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes		<u>30</u>	Steady Flow <u>NO</u>	
10 minutes		<u>30</u>	Surges <u>NO</u>	
15 minutes		<u>30</u>	Down to Nothing <u>0 sec</u>	
20 minutes			Nothing <u>YES</u>	
25 minutes			Gas <u>NO</u>	
30 minutes			Gas & Water <u>NO</u>	
			Water <u>NO</u>	



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD Ops INTERMEDIATE _____

REMARKS:

By ISAAC BASS Witness _____

(Position)