NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
Aztec District Office
1000 Rio Brazos Road
Aztec NM 87410
(505) 334-6178 FAX: (505) 334-6170
http:\lemnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6-9-04 Operate PA	ATINA SAN JUAN, INC.	_API#30-	039-21522
Property Name CHAMPLIN Well Pressure (Shut-in or Producing) T			
OPEN BRADENHEAD AND IN	TERMEDIATE TO ATMOSPHI	ERE INDIVIDUALI	LY FOR 15 MINUTES EACH
PRESSURES: TIME INTERMEDIATE CASING		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes 50	Steady Flow		
10 minutes	Surges		
15 minutes	Down to Nothing	g	
20 minutes	Nothing	8	
25 minutes	Gas	, 	18 13 7475
30 minutes	Gas & Water		JUL 2004
	Water		C PROBLEM S
If bradenhead flowed water, check all of the descriptions that apply below:			
CLEARFR	ESHSALTY	SULFUR	BLACK
5 MINUTE SHUT-IN BRADENHEAD	INTERMEDIATE		
By Karry Buyham Pumper	Witness		
(Position)	_		