



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emmr.state.nm.us/ocd/DistrictIII/3district.htm>

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 6.6.04 Operator Dominion E.+P. API #30-0 39-06727.00.00

Property Name MKL Well No. 5 Location: Unit 2 Section 6 Township 26N Range 7

Well Status(Shut-In or Producing) Tubing 133 Intermediate Casing N/A Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes			Steady Flow	
10 minutes			Surges	
15 minutes			Down to Nothing	
20 minutes			Nothing <u>X</u>	
25 minutes			Gas	
30 minutes			Gas & Water	
			Water	


If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE

REMARKS:

Tubing cemented in inside casing



By Jam Stalle
Lease Operator
(Position)

Witness