



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

<http://emnr.state.nm.us/ocd/District/III/3distric.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-30-12 Operator Burlington API #30-0 39-23501
Property Name Sun Valley Well No. 1124 Location: Unit 26 Section 26 Township 30 Range 6
Well Status (Shut-In or Producing) Initial PSI: Tubing 249 Intermediate 0 Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	0	0	1.2
10 min	0	0	0	0	1.3
15 min	0	0	0	0	1.4
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

Steady Flow	
Surges	
Down to Nothing	/
Nothing	
Gas	DIST. 3
Gas & Water	OIL CONS. DIV.
Water	RCVD JUL 30 '12

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

BH full when opened
Int - dead at 2 minutes

By [Signature]
(Position)

Witness Monica Kuehling
Will dig out valve and let
know if open

E-mail address _____