



AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7-28-04 Operator CDX R.O., LLC API # 300392253

Property Name Jicarilla Cont 156 #029 Location: Unit F Section 32 Township 26 Range 5
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 40 Intermediate _____ Casing 60 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH


Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>0</u>					Steady Flow	
10 minutes						Surges	
15 minutes						Down to Nothing <u>X</u>	
20 minutes						No Flow	
25 minutes						Gas	
30 minutes						Gas and Water	
5 minute SI						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 0 Intermediate _____

REMARKS:



Danell Spear
TECH

Witness _____

(Position)

NMOCD Test Area: