



NEW MEXICO DEPARTMENT OF ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

Oil CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7-14-04 Operator CDX Rio LLC API # 3003922892

Property Name Romero Com #1 Location: Unit P Section 25 Township 26 Range 6
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 120[#] Intermediate Casing 100[#] Bradenhead 0[#]

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Flow Description	Bradenhead Flowed	Intermediate Flowed
	BH- Blowdown	Casing- Monitor	Intermediate- Monitor	Intermediate- Blowdown	Casing- Monitor			
5 minutes	<u>0</u> [#]					Steady Flow		
10 minutes						Surges		
15 minutes						Down to Nothing		
20 minutes						No Flow <u>X</u>		
25 minutes						Gas		
30 minutes						Gas and Water		
5 minute St						Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead 0[#] Intermediate

REMARKS:

Harry Whitson
Tech T.P.S
(Position)

Witness Darrell Spear T.P.S

NMOCD Test Area:

