



AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7-29-04 Operator CDX Rio, LLC API # 3003923068

Property Name Sicarilla CC 155 A #001 Location: Unit H Section 32 Township 26 Range 5
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 95[#] Intermediate Casing 90[#] Bradenhead 0[#]

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH


Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>0[#]</u>					Steady Flow	
10 minutes						Surges	
15 minutes						Down to Nothing	
20 minutes						No Flow <u>X</u>	
25 minutes						Gas	
30 minutes						Gas and Water	
5 minute SI						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead 0 Intermediate

REMARKS:



Danell Spear
TECH

(Position)

Witness

Harry Whitson

NMOCD Test Area: