



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 10/12/04 Operator CDX API # 3003908148
Property Name LICARILLA C8 Location: Unit (E) Section 13 Township 26N Range 5W
(Well Name and Number)
Pressure (Shut-in or Producing) _____ Tubing 30 Intermediate _____ Casing 35 Bradenhead 30

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH


Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>0</u>	<u>35</u>				Steady Flow	
10 minutes	<u>0</u>	<u>35</u>				Surges	
15 minutes	<u>0</u>	<u>35</u>				Down to Nothing	☒
20 minutes	<u>0</u>	<u>35</u>				No Flow	
25 minutes	<u>0</u>	<u>35</u>				Gas	☒
30 minutes	<u>0</u>	<u>35</u>				Gas and Water	
5 minute SI	<u>Test</u>	<u>35</u>				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

MARKS:

Blew down to nothing within 5 mins.
5 min SI - start building up.



Vince Mondragon
Field Tech

Witness _____

(Position)

NMOCD Test Area: C