



AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7-14-04 Operator C DX Rio, LLC API # 3003922296

Property Name Jicarilla A #4E Location: Unit D Section 19 Township 26 Range 5
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 130[#] Intermediate _____ Casing 65[#] Bradenhead 10[#]

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Steady Flow	Surges	Down to Nothing	No Flow	Gas	Gas and Water	Water
	BH- Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor							
5 minutes												
10 minutes												
15 minutes												
20 minutes												
25 minutes												
30 minutes												
5 minute St												

Bradenhead Intermediate
Flowed Flowed


X 1 min

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 0[#] Intermediate _____

REMARKS:



Harry Whitson
Tech T.P.S.
(Position)

Witness

Danell Spear T.P.S.

NMOCD Test Area: