

**NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT**

**OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>**

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test

10/12/04

Operator

CPK

API # 3803922576

Property Name

ИКАРКА С 7Е

Location: Unit

Location: Unit 0 Section 13 Township 26 Range 5W

Section 12

Township

Range 2.5

(Well Name and Number)

Pressure (Shut-in or Producing)

Tubing

30

Intermediate

Casing

90

Bradenhead

TSTM

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead	Intermediate
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	B.T.M	90				Steady Flow	✓	
10 minutes	B.T.M	90				Surges		
15 minutes		90				Down to Nothing		
20 minutes		90				No Flow		
25 minutes		90				Gas	✓	
30 minutes	↓	90				Gas and Water		
5 minute SI	↓	90				Water		

If bradenhead flowed water, check all of the descriptions that apply below:


Clear **Fresh** **Salty** **Sulfur** **Black**

REMARKS:

REMARKS: Well vented but could not measure on a 30/16 gauge.
Never changed slowly vent. Breathing.

Univ. Minn.
Field Tech.

(Position)

Witness

NMOCD Test Area: C