



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test

10/12/04

Operator

CDX

API #

Property Name

JIC AP TRIM 151-1E

Location: Unit

3E/4 3E/4 (P)

Section 10

Township 26N

Range 32W

(Well Name and Number)

Pressure (Shut-in or Producing)

Tubing

50

Intermediate

25

Casing

70

Bradenhead

12

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH


Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	TSTM	70	25	0	70		
10 minutes	TSTM	70	25	0	70		
15 minutes	TSTM	70	25	0	70		
20 minutes	TSTM	70	25	0	70		
25 minutes	TSTM	70	25	0	70		
30 minutes	TSTM	70	25	0	70		
5 minute SI	TSTM	70	25	0	70		
						Steady Flow	
						Surges	Breathing
						Down to Nothing	✓
						No Flow	
						Gas	✓
						Gas and Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

REMARKS:

About 15 min into test. BH was surging. TSTM vapors



Witness

Vince Montoya
Field Tech

(Position)

NMOCD Test Area: C