



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test

10/12/04

Operator

CDX

API #

5003923067

Property Name

LA APACHE 102-13R

Location: Unit

SE 1/4 NE 1/4 (H)

Section

10

Township

26N

Range 4W

(Well Name and Number)

Pressure (Shut-in or Producing)

Tubing

195

Intermediate

Casing

210

Bradenhead

30

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH


Time	Bradenhead			Intermediate		Steady Flow	Surges	Down to Nothing	No Flow	Gas	Gas and Water	Water
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor							
5 minutes	0	210										
10 minutes	0	210										
15 minutes	0	210										
20 minutes	0	210										
25 minutes	0	210										
30 minutes	0	210										
5 minute SI	0	210										

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

REMARKS:

Blew down to 0 in 2 mins.



Witness

Vince Montoya
Field Tech

(Position)

NMOCD Test Area: C