

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30-039-23934

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Burlington Resources Oil & Gas Company	Contact Crystal Tafoya
Address 3401 East 30th St, Farmington, NM	Telephone No. (505) 326-9837
Facility Name: San Juan 30-6 Unit 400	Facility Type: Gas Well

Surface Owner Bureau of Reclamation	Mineral Owner Federal	Lease No. NMNM-012573
--------------------------------------------	------------------------------	------------------------------

LOCATION OF RELEASE

Unit Letter M	Section 14	Township 30N	Range 7W	Feet from the 300'	North/South Line South	Feet from the 990'	East/West Line West	County Rio Arriba
-------------------------	----------------------	------------------------	--------------------	------------------------------	----------------------------------	------------------------------	-------------------------------	-----------------------------

Latitude 36.80604°N Longitude 107.5451°W

NATURE OF RELEASE



Type of Release Gas Release	Volume of Release 95 mcf	Volume Recovered: -0-
Source of Release N/A	Date and Hour of Occurrence: 7/11/12	Date and Hour of Discovery: 7/13/12 at 2:30 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? N/A <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.* N/A	RCVD JUL 31 '12 OIL CONS. DIV. DIST. 3
---------------------------------------------------------------	-------------------------------------------------------

Describe Cause of Problem and Remedial Action Taken.* The discharge pipe on the compressor skid corroded and resulted in a pin hole in the pipe.

Describe Area Affected and Cleanup Action Taken.* N/A - Dry gas, no fluid released

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Crystal Tafoya	Approved by District Supervisor: 	
Title: Field Environmental Specialist	Approval Date: 7/31/2012	Expiration Date:
E-mail Address: crystal.tafoya@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 7/30/12 Phone: (505) 326-9837		

* Attach Additional Sheets If Necessary

nJK 12 213 53814