

Sept 13, 2011

RCVD AUG 30 '12

OIL CONS. DIV.

DIST. 3

Thompson Eng & Production Corp.
7415 E Main
Farmington , NM
87402

This letter is to certify that D & D Services LLC did run deviation surveys at the below listed depths on your Glade Park # 1 in San Juan County

Glade Park # 1 Sec 9 T 29N R13 W


125' 1/2

445' 3/4

1025 1

To the best of my knowledge, I swear this information to be true.

Sincerely,



Glen Davis
Drilling Manager

