



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emrfd.state.nm.us/ocd/District III/3district.htm](http://emrfd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 4-19-10 Operator Four Star Oil & Gas API #30-0 39-18214

Property Name JICARILLA C Well No. 13 Location: Unit B Section 33 Township 25N Range 05W

Well Status (Producing) Tubing 304 Intermediate N/A Casing 43 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>43</u>		
10 min	<u>0</u>		<u>43</u>		
15 min	<u>0</u>		<u>43</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>XX</u>
Nothing	
Gas	<u>XX</u>
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

Oil Cons. Div
District III

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE _____

JUL 20 2012

REMARKS: Bradenhead pressure blew down to zero in 1 second.

By Bruce Martin
by April E. Boh
Position

Witness _____

E-mail address _____