



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/oilcons/DistrictIII/district.htm>
Oil Cons. Div
District III

AUG 20 2012

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8/13/2012 Operator Bad Hills GR API #30-0 39-24087

Property Name JIC 459 Well No. 1 Location: Unit 18 Section 18 Township 30N Range 35E

Well Status (Shut-In or Producing) Initial PSI: Tubing 23 Intermediate Casing 25 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
5 min	0		25		
10 min	0		25		
15 min	0		25		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing ☒	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE

REMARKS:

nothing through out test

By Robert Talamante Witness

lease operator
(Position)

E-mail address