



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

**BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test 8/27/2010 Operator Chevron Midcontinent, L.P. API #30-0 39-06856

Property Name RINCON UNIT Well No. 126 Location: Unit N Section 27 Township 27N Range 06W

Well Status (Producing) Tubing 35 Intermediate N/A Casing 1 Bradenhead 27

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>1</u>		
10 min	<u>0</u>		<u>1</u>		
15 min	<u>0</u>		<u>1</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow <u>XX</u>	
Surges	
Down to Nothing	
Nothing	
Gas <u>XX</u>	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

Oil Cons. Div  
District III

JUL 20 2012

5 MINUTE SHUT-IN PRESSURE BRADENHEAD <1 INTERMEDIATE \_\_\_\_\_

REMARKS: The Bradenhead blew down to a steady whisper in 3 minutes.

By Bruce Martin  
by April E. Pohl  
(Position)

Witness \_\_\_\_\_

E-mail address \_\_\_\_\_