



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/district.htm](http://emnrd.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 8/26/2010 Operator Chevron Midcontinent, L.P. API #30-0 39-06917

Property Name RINCON UNIT Well No. 135 Location: Unit B Section 29 Township 27N Range 06W

Well Status (Producing) Tubing 41 Intermediate 0 Casing 41 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>41</u>	<u>0</u>	<u>41</u>
10 min	<u>0</u>		<u>41</u>	<u>0</u>	<u>41</u>
15 min	<u>0</u>		<u>41</u>	<u>0</u>	<u>41</u>
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	<u>0</u>	<u>0</u>
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

Oil Cons. Div
District III
JUL 20 2012

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS: MV/DK dual completion well.

By Bruce Martin
by April E Pohl
(Position)

Witness _____

E-mail address _____