



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/district.htm](http://emnrd.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 8/20/2010 Operator Chevron Midcontinent, L.P. API #30-0 39-06918

Property Name RINCON UNIT Well No. 127 Location: Unit A Section 28 Township 27N Range 06W

Well Status (Producing) Tubing 111 Intermediate 320 Casing 111 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE					FLOW CHARACTERISTICS	
	Bradenhead		INTERM			BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int			
5 min	<u>0</u>	<u>320</u>	<u>111</u>	<u>flowing</u>	<u>111</u>	Steady Flow	<u>XX</u>
10 min	<u>0</u>	<u>320</u>	<u>111</u>	<u>0</u>	<u>111</u>	Surges	
15 min	<u>0</u>	<u>320</u>	<u>111</u>	<u>0</u>	<u>111</u>	Down to Nothing	
20 min						Nothing	<u>XX</u>
25 min						Gas	<u>XX</u>
30 min						Gas & Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 1

REMARKS: The Intermediate blew down to a steady whisper in 9.5 minutes.

By Bruce Martin
by April E Pohl
Position

Witness _____

E-mail address _____

Oil Cons. Div
District III

JUL 20 2012