



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distr.htm](http://emnrd.state.nm.us/ocd/District%20III/3distr.htm)

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 9/3/2010 Operator Chevron Midcontinent, L.P. API #30-0 39-07034

Property Name RINCON UNIT Well No. 156 Location: Unit M Section 16 Township 27N Range 06W

Well Status (Producing) Tubing 62 Intermediate N/A Casing 73 Bradenhead vacuum

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>73</u>		
10 min	<u>0</u>		<u>73</u>		
15 min	<u>0</u>		<u>73</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	BRADENHEAD	INTERMEDIATE
	<u>XX</u>	
Vacuum		
Steady Flow		
Surges		
Down to Nothing		
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE _____

REMARKS: The Bradenhead line was on a slight vacuum.

By Bruce Martin
by April E Pohl
(Position)

Witness _____

E-mail address _____

Oil Cons. Div
District III
JUL 20 2012