



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 9/22/2010 Operator Chevron Midcontinent, L.P. API #30-0 39-26566

Property Name RINCON UNIT Well No. 156M Location: Unit I Section 16 Township 27N Range 06W

Well Status (Producing) Tubing 38 Intermediate 62 Casing 97 Bradenhead 8

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead Int	Csg	INTERM Int	Csg
TIME					
5 min	0	62	97		
10 min	0	62	97		
15 min	0	62	97		
20 min				0	97
25 min				0	97
30 min				0	97

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	XX
Nothing	
Gas	XX
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

Oil Cons. Div
District III

JUL 20 2012

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS: The Bradenhead line blew down to nothing in 5 seconds. The Intermediate line blew down to nothing in 20 seconds

By Bruce Martin
by April E. Pohl
(Position)

Witness _____

E-mail address _____