



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 8/2/2010 Operator Chevron Midcontinent, L.P. API #30-0 39-26568

Property Name RINCON UNIT Well No. 130M Location: Unit I Section 32 Township 27N Range 06W

Well Status (Producing) Tubing 88 Intermediate 0 Casing 101 Bradenhead 5

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>0</u>	<u>101</u>		
10 min	<u>0</u>	<u>0</u>	<u>101</u>		
15 min	<u>0</u>	<u>0</u>	<u>101</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>XX</u>
Nothing	
Gas	<u>XX</u>
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE _____

REMARKS: The Bradenhead line blew down to nothing in 3 seconds.

By Bruce Martin
by April E Pohl
(Position)

Witness _____

E-mail address _____

Oil Cons. Div
District III

JUL 20 2012