



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX. (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 8/20/2010 Operator Chevron Midcontinent, L.P. API #30-0 39-26628

Property Name RINCON UNIT Well No. 181M Location: Unit F Section 22 Township 27N Range 06W

Well Status (Producing) Tubing 108 Intermediate 84 Casing 36 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
5 min	0	84	36	0	36
10 min	0	84	36	0	36
15 min	0	84	36	0	36
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		XX
Surges		
Down to Nothing		
Nothing	XX	
Gas		XX
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

Oil Cons. Div
District III

JUL 20 2012

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE <1

REMARKS: The Intermediate line blew down to vapors in 12 seconds.

By Bruce Martini
by April E Pohl
(Position)

Witness _____

E-mail address _____