



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3district.htm>

RCVD SEP 11 '12
OIL CONS. DIV.
DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9-11-12 Operator BP America API #30-0 45-08335

Property Name Muslow Gas Co Well No. 1 Location: Unit F Section 15 Township 29 Range 12

Well Status(Shut-In or Producing) Initial PSI: Tubing 30 Intermediate N/A Casing 160 Bradenhead 44

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>160</u>		
10 min	<u>0</u>		<u>160</u>		
15 min	<u>0</u>		<u>160</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>/</u>
Nothing	
Gas	<u>/</u>
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 38 INTERMEDIATE _____

REMARKS:

Puffb when opened. Stuffed box leak. Called
Buddy Shero - On 5 min shut in came back to 38 lbs
No H₂S detected.

By Ray Johnson
Heck
(Position)

Witness Monica Kuebling
Regist. Schematic

E-mail address _____