



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrdr.state.nm.us/ocd/District III/3district.htm](http://emrdr.state.nm.us/ocd/District%20III/3district.htm)

RCVD SEP 11 '12
OIL CONS. DIV.
DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9-11-12 Operator BP America API #30-0 45-24008
Property Name Buena Vista Well No. 1E Location: Unit 0 Section 15 Township 29 Range 12
Well Status (Shut-In or Producing) Initial PSI: Tubing 159 Intermediate N/A Casing 160 Bradenhead 41

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead				
	BH	Int	Csg	Int	Csg
TIME	<u>2.9</u>		<u>159</u>		
5 min	<u>1.5</u>		<u>155</u>		
10 min	<u>2</u>		<u>155</u>		
15 min	<u>0</u>		<u>155</u>		
20 min	<u>0</u>		<u>155</u>		
25 min	<u>0</u>		<u>155</u>		
30 min	<u>0</u>		<u>155</u>		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	<u>to vapors</u>	
Surges		
Down to Nothing		
Nothing		
Gas	<u>✓</u>	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 3

INTERMEDIATE N/A

REMARKS:

Hard blow 20 seconds - to Med blow to Med light
at 40 surging at 1 min. light blow surging at 3.
light blow to vapors for 30 minutes

By Roy Jolesma
Jack
(Position)

Witness Moussa Kuchling
request schematic
no H₂S detected

E-mail address _____