



# NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

## BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 7-6-10 Operator Four Star Oil & Gas API #30-0 39-06928

Property Name RINCON UNIT Well No. 84 Location: Unit A Section 26 Township 27N Range 07W

Well Status (Producing) Tubing 21 Intermediate N/A Casing 45 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>45</u>		
10 min	<u>0</u>		<u>45</u>		
15 min	<u>0</u>		<u>45</u>		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	<u>XX</u>	
Nothing		
Gas	<u>XX</u>	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

Oil Cons. Div  
District III

JUL 20 2012

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE \_\_\_\_\_

REMARKS: The Bradenhead valve blew down to zero in 1 second.

By Brade Martini  
by April E Pohl  
(Position)

Witness \_\_\_\_\_

E-mail address \_\_\_\_\_