

NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District.lfl/3distric.htm

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 4-26-18					Operator [Four Star Oil & Gas] API #30-0 39-22970				
Property Name LYDIA RENTZ Well No. 8 Location: Unit C Section 19 Township 25N Range 03W									
Well Status (<u>Producing</u>) Tubing 307 Intermediate N/A Casing 413 Bradenhead 3									
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH									
Testing	BH Int Csg Int Csg						FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE		
TIME 5 min_	0		413			Steady Flow			
10 min_	0		413			Surges			
15 min_	0		412			Down to Not	thing XX		
20 min_						Nothing			
25 min_						Gas	XX		
30 min_						Gas & Water	•		
		•		ľ	·	Water			
If bradenhead flowed water, check all of the descriptions that apply below: Oil Cons. Div									
	CLEA	R	FRESH	S	ALTY_	SULFUR	BLACK	-	District III
									IL 2 0 2012
5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE REMARKS: Bradenhead pressure bled down to zero in 1 second.									
KEWIAR		radennea	<u> pressui</u>	e bled dow	n to zero	o in 1 second.			
							<u></u>		
	, ——	144							
By Bruce Martin Witness Witness									
-b	Up C	Spi	l <i>Efl</i>	shif					
E-mail a	•	()	•						