



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX. (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 4-26-10 Operator Four Star Oil & Gas API #30-0 39-25316

Property Name LYDIA RENTZ Well No. 9 Location: Unit N Section 20 Township 25N Range 03W

Well Status (P/A) Tubing ☐ Intermediate N/A Casing ☐ Bradenhead ☐

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME					
5 min					
10 min					
15 min					
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE BRADENHEAD ☐ INTERMEDIATE ☐

REMARKS: Well is plugged and abandoned.

By Bruce Martin
by April E Pohl
(Position)

Witness ☐

E-mail address ☐

Oil Cons. Div
District III

JUL 20 2012