



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
[http://emnrd.state.nm.us/ocd/District III/district.htm](http://emnrd.state.nm.us/ocd/District%20III/district.htm)

**BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test 4-26-10 Operator Four Star Oil & Gas API #30-0 39-25377

Property Name LYDIA RENTZ Well No. 11A Location: Unit N Section 19 Township 25N Range 03W

Well Status (Producing) Tubing 194 Intermediate N/A Casing 194 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					FLOW CHARACTERISTICS	
	Bradenhead		INTERM			BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
TIME							
5 min	<u>0</u>		<u>194</u>			Steady Flow	
10 min	<u>0</u>		<u>194</u>			Surges	
15 min	<u>0</u>		<u>194</u>			Down to Nothing	<u>XX</u>
20 min						Nothing	
25 min						Gas	<u>XX</u>
30 min						Gas & Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

Oil Cons. Div  
District III

JUL 20 2012

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE \_\_\_\_\_

REMARKS: The Bradenhead pressure blew down to zero in 1 second.

By Bruce Martini  
by April E. Pohl  
Position \_\_\_\_\_

Witness \_\_\_\_\_

E-mail address \_\_\_\_\_